# Walking working surfaces 1910.22

## Surface conditions. The employer must ensure:

## 1910.22(a)(1)

All places of employment, passageways, storerooms, service rooms, and walking-working surfaces are kept in a clean, orderly, and sanitary condition.

# 1910.22(a)(2)

The floor of each workroom is maintained in a clean and, to the extent feasible, in a dry condition. When wet processes are used, drainage must be maintained and, to the extent feasible, dry standing places, such as false floors, platforms, and mats must be provided.

## 1910.22(a)(3)

Walking-working surfaces are maintained free of hazards such as sharp or protruding objects, loose boards, corrosion, leaks, spills, snow, and ice.

## 1910.22(b)

*Loads.* The employer must ensure that each walking-working surface can support the maximum intended load for that surface.

#### <u>1910.22(c)</u>

<u>Access and egress.</u> The employer must provide, and ensure each employee uses, a safe means of access and egress to and from walking-working surfaces.

## 1910.22(d)

#### Inspection, maintenance, and repair. The employer must ensure:

#### 1910.22(d)(1)

Walking-working surfaces are inspected, regularly and as necessary, and maintained in a safe condition.

#### 1910.22(d)(2)

Hazardous conditions on walking-working surfaces are <u>corrected or repaired before an employee uses the</u> <u>walking-working surface again.</u> If the correction or repair cannot be made immediately, the hazard must be guarded to prevent employees from using the walking-working surface until the hazard is corrected or repaired; and

## 1910.22(d)(3)

When any correction or repair involves the structural integrity of the walking-working surface, a **qualified person** performs or supervises the correction or repair.